

600 SW JEFFERSON ST, SUITE 300 LEE'S SUMMIT, MISSOURI 64063 (816) 399 -4901

Г			1		1		
Colby Shaw				ction Date	Time		
			5/20/2021		11:00		
Address	Address City			it #	Owner/Builder		
2125 NW Ashurst Dr Lee's Summit			20211220		Summit Homes		
Inspection Type			Subdivision		1	Lot #	
Footing			Woodside Ridge		37		
Site Conditions (all m	nust c	omply if applicable)	Sla	ab (Basement or Gara	ge As Marke	<u>d)</u>	
<ul> <li>Erosion control is in place and functional (inspection shall not be performed if erosion control is not functionally in compliance with the City requirements).</li> <li>Soils – bearing capacity as determined by:         <ul> <li>Bearing on undisturbed soil @ 1,500 psf</li> <li>Per engineer report (comment or attach report)</li> </ul> </li> </ul>				<ul> <li>Formed &amp; Reinforced Per City Approved Dwgs</li> <li>Garage structural slab per approved plan</li> <li>Basement slab on grade per approved plan</li> <li>6 mil vapor barrier installed – not required for garage slab</li> <li>Isolation rings or block-outs are provided over pier pads for columns</li> </ul>			
Cold weather protection				Footings			
Foundation Wall Elements         Wall forms centered on footings         Wall thickness as specified on approved plans         Reinforcement installed per approved plans         Hold downs placed and installed properly         Wall openings installed in accordance with         City approved plans         Deck/porch/balcony columns         Top of wall and steps formed a minimum of 8" above         proposed grading contours.         Max. 12" block down at garage doors.         Ufer Ground attachment rod left exposed         (Give approx. location in comments)         Retaining walls (for multiple walls on the plot plan         clarify which walls are being inspected in the         comments)         Installation per approved plans				<ul> <li>Reinforced per city approved plans or engineer report</li> <li>Deck/porch/balcony footings</li> <li>Footing – width, depth and location per approved plans an or engineer report</li> <li>Solid jumps</li> <li>Frost depth (min. 36 inches)</li> <li>Column pads – basement</li> <li>Column/pad at garage structural slab</li> </ul>			
Comments:	ea pia						
		tion of rebar are installed p Ufer rod is located near th				ngs	
This is to certify that I, or qualifie direction, inspected and/ or test accordance with the applicable C	ed the al	bove checked items in			STE OF	F MISSON	

Signed:

approved plans and specifications.

141

codes and engineering details. The work is complete and to the best of my knowledge was found to be in substantial compliance with the

Date:

5/20/2021

