



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20211673, Public Works Right of Way Permit
Address: 1537 SW ARBOR FALLS DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Tuesday, June 01, 2021

Corrective Action Required

1 Misc

Site visit: The line has not been buried yet. I reached out Lantel to see if they have an update. The wire appears to run under the street to an AT&T pedestal in a vacant lot.

Comments: