

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20204474, Public Works Right of Way Permit Address: 1813 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Matt Munger Passed Wednesday, June 02, 2021

Corrective Action Required

1 Misc Site Visit - GF drop has been installed.

Comments: