

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204103
Address: 129 NW MACKENZIE DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Gas Service Inspection - Residential	John Morris	Failed	Wednesday, June 02, 2021

Corrective Action Required:

1	Misc	Gas piping is prohibited in return air plenums, master suite RA under great room fireplace. G2415.3
---	------	---

Corrective Action Required:

2	Misc	Unable to verify this issue has been resolved
---	------	---

Comments: