## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20191614

Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Robb Popp Partial Friday, June 04, 2021

Commercial

Informational:

1 THIRD FLOOR —AREAS APPROVED—

\*\*\*BUIDING C\*\*\*

ROOMS:3019-3031

-STAIRWELL WALLS AND CEILING CORRIDOR TO SHAFT WALL SOFFIT FRAMING IN CORRIDOR

\*\*\*BUILDING B\*\*\*

**CORRIDOR TO SHAFT WALL** 

ROOMS: 3003-3016

STAIRWELL WALLS AND CEILING SOFFIT FRAMING IN CORRIDOR STAIRWELL WALLS AND CEILING

\*\*\*BUILDING A\*\*\*\*

ROOMS: 3001, 3002, 3017, 3018, 3037, 3038, 3039, 3041, 3042, 3043, 3044, 3045,

3047

**CORIDOOR TO SHAFT WALL** 

Informational:

2 SECOND FLOOR — AREAS APPROVED—

\*\*\*BUILDING C\*\*\*

ROOMS: 2019-2031

CORRIDOR WALLS AND CEILING STAIRWELL WALLS AND CEILING

\*\*\*BUILDING B\*\*\*

ROOMS: 2003-2017

CORRIDOR WALLS AND CEILINGS \line STAIRWELL WALLS AND CEILING

\*\*\*BUILDING A\*\*\*

CORRIDOR CEILINGS TO SHAFT WALL ROOMS: 2001,2002, 2017,2018,2040-2045

STAIRWELL WALLS AND CEILING

Informational:

FIRST FLOOR —AREAS APPROVED—

\*\*\*BUILDING C\*\*\*

CORRIDOR CEILINGS TO SHAFT WALL

ROOMS:1015,1017,1020-1030 STAIRWELL WALLS AND CEILING

\*\*\*BUILDING B\*\*\*

CORRRIDOR CEILNGS TO SHAFT WALL

ROOMS: 1002-1015

\*\*\*BUIDING A\*\*\*

CORRIDOR CEILNG TO SHAFT WALL EXTERIOR WALL 1032 OK TO INSULATE

\*\*MCAL BUILDING\*\*

PRE ROCK:

MECHANICAL ROOM 165 NORTH WALL

ROOM 1057 OK TO ROCK FOR ELECTRICAL GEAR EAST AND SOUTH WALLS

STAIRWELL WALLS AND CEILING

Corrective Action Required:

4 Miscellaneous Correction

-EXPOSE AND SEAL PENETRATIONS AT SHAFT WALL PER ULLISTING

\*\*\*5-28\*\*\*

2035A- FLASH OPENINGS 2047-NOT INSPECTED

3047- COMPLETE STORM DRAIN

\*\*\*6-4\*\*

- -H2.5 AT STAIRWELL 3A, PROTECT NM STAIRWELL 1B
- -SHAFT PENETRATION PER UL AT 1002 MECHANICAL CLOSET

## **Comments:**