



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20211910, Public Works Right of Way Permit  
Address: 153 NW CARSON DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

|                              |             |          |                        |
|------------------------------|-------------|----------|------------------------|
| Inspection:                  | Inspector:  | Outcome: | Date:                  |
| <b>Site Visit Inspection</b> | Matt Munger | Partial  | Tuesday, June 08, 2021 |

Corrective Action Required

|   |      |                                                   |
|---|------|---------------------------------------------------|
| 1 | Misc | Site Visit - The line has not been installed yet. |
|---|------|---------------------------------------------------|

**Comments:**