

RESIDENTIAL ENGINEERING SERVICES

600 SW JEFFERSON ST, SUITE 300 LEE'S SUMMIT, MISSOURI 64063 (816) 399 -4901

ENGINEERING + DESIGN						
Inspector		Inspection Date		Time		
Colby Shaw		5/10/2021		1:30		
Address City		Perm	it #	Owner/Builder		
1529 SW Georgetown Dr Lee's Summit		PR	RES20211038	Summit Homes		
Inspection Type		Subdivision			Lot #	
Foundation		Reserve at Stoney Creek		k	72	
Site Conditions (all must c	omply if applicable)	Sla	b (Basement or Gara	ge As Markeo	<u>(k</u>	
 Erosion control is in place and functional (inspection shall not be performed if erosion control is not functionally in compliance with the City requirements). Soils – bearing capacity as determined by: Bearing on undisturbed soil @ 1,500 psf Per engineer report (comment or attach report) Cold weather protection 			Formed & Reinforced Per City Approved Dwgs Garage structural slab per approved plan Basement slab on grade per approved plan 6 mil vapor barrier installed – not required for garage slab Isolation rings or block-outs are provided over pier pads for columns otings			
			Reinforced per city approved plans or engineer report			
 Foundation Wall Elements Wall forms centered on footings Wall thickness as specified on approved plans Reinforcement installed per approved plans Hold downs placed and installed properly Wall openings installed in accordance with City approved plans Deck/porch/balcony columns Top of wall and steps formed a minimum of 8" above proposed grading contours. Max. 12" block down at garage doors. 			 Footing – width, depth and location per approved plans a or engineer report 			
					k piersj	
			Pier foundation per approved plan			
 Ufer Ground attachment rod left exposed (Give approx. location in comments) 			Size: Depth:			
Retaining walls (for multiplication in complexity) clarify which walls are bein comments) Installation per approved plan	e walls on the plot plar g inspected in the	ı	Bearing:			
Comments:						
Concrete forms and installa Foundation is approved for garage.	-	-				
This is to certify that I, or qualified individ direction, inspected and/ or tested the al accordance with the applicable City appr codes and engineering details. The work of my knowledge was found to be in sub approved plans and specifications.	bove checked items in oved building and site plans, is complete and to the best			STIL OI	ADLEY	



141

Date:

5/10/2021

