

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210296
Address: 119 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Michael Harkins	Failed	Wednesday, June 16, 2021

Corrective Action Required:

1	Misc	-Install exterior doors and windows -Minimum 12" field 6" edge exterior sheathing fastening-NOT COMPLETE AT BACK NORTH AND SOUTH CORNER SHEETS -Fireblock plate Penetrations throughout-SEAL BASEMENT BEAM POCKETS / SOFFIT SE CLOSET -Provide engineered solution for repair of field altered trusses, South wall TRIPLE GIRDER & TRUSS TO WEST OF TRIPLE : OK TO INSULATE :
---	------	---

Comments: