



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20212405, Public Works Right of Way Permit

Address: 107 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:

Inspector:

Outcome:

Date:

Site Visit Inspection

Matt Munger

Partial

Thursday, June 17, 2021

Corrective Action Required

1 Misc

Site Visit - The line has not been installed yet.

Comments: