

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20191614
Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Robb Popp	Partial	Tuesday, June 22, 2021

Informational:
1 THIRD FLOOR

— AREAS APPROVED —

BUILDING C

ROOMS: 3019-3031
-STAIRWELL WALLS AND CEILING
CORRIDOR TO SHAFT WALL
SOFFIT FRAMING IN CORRIDOR

BUILDING B

CORRIDOR TO SHAFT WALL
ROOMS: 3003-3016
STAIRWELL WALLS AND CEILING
SOFFIT FRAMING IN CORRIDOR
STAIRWELL WALLS AND CEILING

BUILDING A

ROOMS: 3001, 3002, 3017, 3018, 3037, 3038, 3039, 3041, 3042, 3043, 3044, 3045, 3047
CORRIDOR TO SHAFT WALL

Informational:	2 SECOND FLOOR	<p>STAIRWELL WALLS AND CEILING</p> <p>— AREAS APPROVED —</p> <p>***BUILDING C***</p> <p>ROOMS: 2019-2031 CORRIDOR WALLS AND CEILING STAIRWELL WALLS AND CEILING</p> <p>***BUILDING B***</p> <p>ROOMS: 2003-2017 CORRIDOR WALLS AND CEILINGS \line STAIRWELL WALLS AND CEILING</p> <p>***BUILDING A*** CORRIDOR CEILINGS TO SHAFT WALL ROOMS: 2001,2002, 2017,2018,,235,2040-2045 STAIRWELL WALLS AND CEILING</p>
Informational:	3 FIRST FLOOR	<p>— AREAS APPROVED —</p> <p>***BUILDING C*** CORRIDOR CEILINGS TO SHAFT WALL ROOMS:1015,1017,1020-1030 STAIRWELL WALLS AND CEILING</p> <p>***BUILDING B*** CORRRIDOR CEILNGS TO SHAFT WALL ROOMS: 1002-1015 STAIRWELL WALLS AND CEILING</p> <p>***BUIDING A*** CORRIDOR CEILNG TO SHAFT WALL EXTERIOR WALL 1032 OK TO INSULATE STAIRWELL WALLS AND CEILING ROOMS: 1046, 1053, 1056, 1059, 1061, 1062,</p> <p>**MCAL BUILDING** PRE ROCK: MECHANICAL ROOM 165 NORTH WALL ROOM 1057 OK TO ROCK FOR ELECTRICAL GEAR EAST AND SOUTH WALLS STAIRWELL WALLS AND CEILING ROOMS 1018, 1061, 1045,1047,1048</p>
Corrective Action Required:	4 Miscellaneous Correction	<p>-EXPOSE AND SEAL PENETRATIONS AT SHAFT WALL PER UL LISTING</p> <p>***5-28***</p> <p>2047-NOT INSPECTED 3047- COMPLETE MECHANICAL VENT/ DRAIN</p>

***6-4**

-SHAFT PENETRATION PER UL AT 1002 MECHANICAL CLOSET

Comments: