CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20191614

Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Robb Popp Partial Wednesday, June 30,

Commercial

Informational:

1 THIRD FLOOR —AREAS APPROVED—

BUIDING C
COMPLETE

BUILDING B

COMPLETE

BUILDING A*

ROOMS: 3001, 3002, 3017, 3018, 3038, 3039, 3041, 3042, 3043, 3044, 3045, 3047

2021

CORIDOOR TO SHAFT WALL
STAIRWELL WALLS AND CEILING

Informational:

2 SECOND FLOOR —AREAS APPROVED—

BUILDING C

COMPLETE

BUILDING B

COMPLETE

BUILDING A

CORRIDOR CEILINGS TO SHAFT WALL ROOMS: 2001,2002, 2017,2018,2043,2046

STAIRWELL WALLS AND CEILING

Informational:

3 FIRST FLOOR -AREAS APPROVED-

BUILDING C

CORRIDOR CEILINGS TO SHAFT WALL

ROOMS:1015,1017,1020-1030 STAIRWELL WALLS AND CEILING

BUILDING B

CORRRIDOR CEILNGS TO SHAFT WALL

ROOMS: 1002-1015

STAIRWELL WALLS AND CEILING

BUIDING A

CORRIDOR CEILNG TO SHAFT WALL **EXTERIOR WALL 1032 OK TO INSULATE** STAIRWELL WALLS AND CEILING

ROOMS: 1046, 1053, 1056, 1059, 1061, 1062,

MCAL BUILDING

PRE ROCK:

MECHANICAL ROOM 165 NORTH WALL

ROOM 1057 OK TO ROCK FOR ELECTRICAL GEAR EAST AND SOUTH WALLS

STAIRWELL WALLS AND CEILING ROOMS 1018, 1061, 1045, 1047, 1048

Corrective Action Required:

Miscellaneous

2047-NOT INSPECTED Correction 2044-INCOMPLETE 2045-INCOMPLETE

3047- COMPLETE MECHANICAL VENT/ DRAIN

Comments: