

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20203845  
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:   | Inspector: | Outcome: | Date:                 |
|---|------------|----------|-----------------------|
| <b>Underground Electrical<br/>Inspection - Commercial</b> | Robb Popp  | Failed   | Friday, July 09, 2021 |

Informational:

|   |  |   |
|---|--|---|
| 1 | THE FOLLOWING<br>AREAS ARE<br>APPROVED | -Conduit from Southwest corner of building north to CT and Transformer location<br>-Conduit for monument sign at Northeast entrance and Left field Musco light at northeast diamond to west end of NE diamond<br>-Conduit for left field Musco light at NW diamond<br>-Conduit from NW dugout electrical room to scoreboards<br>-Conduit between north fields to NW dugout and field house for musco lights, power and communications |
|---|--|---|

**Comments:**