

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRCOM20202637  
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:                      | Inspector: | Outcome: | Date:                   |
|----------------------------------|------------|----------|-------------------------|
| <b>Rated Assembly Inspection</b> | Robb Popp  | Partial  | Thursday, July 22, 2021 |

Informational:

|   |             |                           |
|---|-------------|---------------------------|
| 1 | FIRST FLOOR | <b>**AREAS APPROVED**</b> |
|---|-------------|---------------------------|

-SHAFT LAYER AT BUILDING A/B SEPARATION WALL BOTH SIDES  
-SCREW PATTERN AND FIRE TAPE SHAFT WALL BUILDING A

Corrective Action Required:

|   |                             |   |
|---|-----------------------------|---|
| 2 | Miscellaneous<br>Correction | -SEAL GAP AT TOP OF SECOND LAYER AND ALL PENETRATIONS AT SHAFT WALL<br>BUILDING A |
|---|-----------------------------|---|

Corrective Action Required:

|   |              |                                 |
|---|--------------|---------------------------------|
| 3 | SECOND FLOOR | -SHAFT WALL LAYER AT BUILDING A |
|---|--------------|---------------------------------|

**Comments:**