

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20191614
Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Robb Popp	Partial	Thursday, July 29, 2021

Informational:
1 THIRD FLOOR —AREAS APPROVED—

BUILDING C
COMPLETE

BUILDING B
COMPLETE

BUILDING A*
-COMPLETE

Informational:
2 SECOND FLOOR —AREAS APPROVED—

BUILDING C
COMPLETE

BUILDING B
COMPLETE

BUILDING A
CORRIDOR CEILINGS TO SHAFT WALL

Informational:	ROOMS: 2001,2002, 2017,2018,2043, 2045,2046, 2047 STAIRWELL WALLS AND CEILING
3 FIRST FLOOR	<p data-bbox="537 247 808 273">—AREAS APPROVED—</p> <p data-bbox="537 317 760 342">***BUILDING C***</p> <p data-bbox="537 352 980 453">CORRIDOR CEILINGS TO SHAFT WALL ROOMS:1015,1017,1020-1030 STAIRWELL WALLS AND CEILING</p> <p data-bbox="537 497 760 522">***BUILDING B***</p> <p data-bbox="537 533 987 634">CORRIDOR CEILINGS TO SHAFT WALL ROOMS: 1002-1015 STAIRWELL WALLS AND CEILING</p> <p data-bbox="537 678 748 703">***BUILDING A***</p> <p data-bbox="537 714 1310 848">CORRIDOR CEILING TO SHAFT WALL EXTERIOR WALL 1032 OK TO INSULATE STAIRWELL WALLS AND CEILING ROOMS: 1046, 1053, 1056, 1059, 1061, 1062, 1037,1038,1049,1052</p> <p data-bbox="537 892 786 917">**MCAL BUILDING**</p> <p data-bbox="537 928 1002 1026">PRE ROCK: MECHANICAL ROOM 165 NORTH WALL STAIRWELL WALLS AND CEILING</p> <p data-bbox="537 1071 1360 1241">ROOMS 1018, 1061, 1045,1047,1048,1057,1057A ROOM 156 OK FOR ROCK BEHIND ELECTRICAL EQUIPMENT ROOM 1041 OK FOR SOFFIT FRAMING ROOMS OK FOR BATHROOM PRE ROCK AND EXTERIOR WALL INSULATION::101-106,108,109-128,,130,131,133,135-137,139,140-146</p>
Corrective Action Required:	
4 Miscellaneous Correction	<p data-bbox="537 1287 760 1312">2044-INCOMPLETE</p> <p data-bbox="537 1323 760 1348">2045-INCOMPLETE</p> <p data-bbox="537 1358 760 1383">024-REPAIR TRUSS</p> <p data-bbox="537 1394 1351 1486">MCAL- -PARTY WALLS-PROVIDE STUD SHOES AT ALL STUDS OVERBORED BY SPRINKLER LINE</p>

Comments: