

600 SW JEFFERSON ST, SUITE 300 LEE'S SUMMIT, MISSOURI 64063 (816) 399 -4901

Inspector		Inspection Date		Time	
Colby Shaw		7/27/2021		10:45	
Address	City	Permit #		Owner/Builder	
4420 SW Alabaster	Lee's Summit	PRRES20213077 Summ		Summit Ho	omes
Inspection Type		Subdivision		Lot #	
Footing		Ma	Manor at Stoney Creek		91
Site Conditions (all must	comply if applicable)	Sla	b (Basement or Gara	ge As Markeo	<u>(k</u>
 Erosion control is in place and functional (inspection shall not be performed if erosion control is not functionally in compliance with the City requirements). Soils – bearing capacity as determined by: Bearing on undisturbed soil @ 1,500 psf Per engineer report (comment or attach report) 			Formed & Reinforced Per City Approved Dwgs Garage structural slab per approved plan Basement slab on grade per approved plan 6 mil vapor barrier installed – not required for garage slab Isolation rings or block-outs are provided over pier pads for columns		
Cold weather protection		Footings			
Gundation Wall Elements Wall forms centered on footings Wall thickness as specified on approved plans Reinforcement installed per approved plans Hold downs placed and installed properly Wall openings installed in accordance with City approved plans Deck/porch/balcony columns Top of wall and steps formed a minimum of 8" above		2 2 2 2 2	 Deck/porch/balcony footings Footing – width, depth and location per approved plans at or engineer report Solid jumps Frost depth (min. 36 inches) Column pads – basement Column/pad at garage structural slab 		
		\checkmark			
		 ✓ 			
			Drilled Piers (refer to footings for deck piers)		
 proposed grading contours. Max. 12" block down at garage doors. Ufer Ground attachment rod left exposed (Give approx. location in comments) <u>Retaining walls</u> (for multiple walls on the plot plan clarify which walls are being inspected in the comments) 			Pier foundation per approved plan Size: Depth: Bearing:		
Installation per approved pl	ans				

Comments:

Concrete forms and installation of rebar are installed per approved plans and specifications. Footings have been spread due to soil conditions. Footings are approved for concrete. Ufer rod is located near the center of the rear garage wall.

This is to certify that I, or qualified individuals working under my direction, inspected and/ or tested the above checked items in accordance with the applicable City approved building and site plans, codes and engineering details. The work is complete and to the best of my knowledge was found to be in substantial compliance with the approved plans and specifications.

Signed:

BUH

Date:

7/27/2021

