CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20202637

Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Underground Electrical Robb Popp Partial Wednesday, August

Inspection - Commercial 04, 2021

Informational:

1 Misc 3/4/21, 3/5/21 - INSPECTED PARTIAL UNDERGROUND CONDUIT FOR JOB

TRAILER TEMP POWER, RUNNING E TO W ALONG N SIDE OF GRAVEL DRIVE

-Conduit in main electrical g110 for first service bundle

-Conduit from main electrical room to areas A, B & C through area D

LIGHT POLES:

-Conduit and ground rods to P30-37-41,43-46, 54,55,56,56B,56A,59,64,65,65A,65B,66-71

Comments: