

Third Party Inspection Report

Inspector	Data	Ι								
	Date	Time								
David P. Ainsworth, P.E.	8-9-21	7:45 AM								
Company	Permit #	Permit Holder								
David P. Ainsworth, P.E.	2021-3690	TRUMARK HOMES								
Inspection Type	Address MONTICEUD L	OT 75								
FOOTING	1217 NE GOSHEN DR LSMO									
E-Mail Address dainsworth@chelepis.com										
Instructions: This form must be completed when performing a third party inspection for any building										
permit in Lee's Summit. Submit form v	vithin 48 hours after inspection to t	he Development Services								
Department. If a subsequent inspection that inspection being scheduled.	n is performed by the City, this form	n must be submitted prior to								
Check all boxes that apply to the site of	onditions and the inspection being p	performed.								
Site Conditions:										
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)										
Erosion controls in place and maintained										
*Note: If these requirements are not met no inspection shall be performed or accepted by the City.										
Foundations and Footings:										
Foundation type and MBOE is equal to or above the plot plan										
Concrete encased electrode (uf	Concrete encased electrode (ufer) ground installed (Location must be noted in comments)									
	Foundation/Footing meets all City Code requirements and matches City approved plans or									
Foundation Walls:										
Elevation is sufficient to achieve	2% slope away from structure									
No openings below the MBOE										
Concrete encased electrode (un	er) ground exposed									
Foundation wall meets all City C engineered design.	ode requirements and matches City	/ approved plans or								



F	l'	a	ì	7	1	100	1	g	9 8
			_	-	•	•	•	മ	•

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

WEER GROUND ROD IS LOCATED ON THE WEST SIDEWALL ABOUT 10' SOUTH OF THE NORTHWEST CORNER.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature:

Danil P. Clineworth PE.

Engineer/Architect Seal