

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210673
Address: 1619 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Patrick Schonfeldt	Failed	Wednesday, August 11, 2021

Corrective Action Required:

1	Misc	-Seal NM top plate penetration at front entry closet -Fireblock between top plate and either foundation wall or framing top plate at finished basement - see East wall at wet bar, East bath - seal NM and pex penetrations through fireblock, remove Kraft paper from insulation, loose insulation used as fireblock must be unfaced -Address floor joist that has been cut for DWV above wet bar - this has been done in between inspections -seal all top plate penetrations at both finished basement bedrooms - see closet walls
---	------	---

Comments: