CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20202286

Address: 2020 SW HOOK RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Water Line - Construction Inspection		John DiMauro	Passed	Thursday, August 12, 2021
Informational:				
1	Misc	On Wednesday, 6-09-2021 Spalding Excavating Had surveyor place stakes for final roadway elevation. Contractor placed geo-grid and began placement of rock sub base and compacted.		
Informational:				
2	Misc	On Thursday, 7-29-2021 Red Ford Excavating began placement of the 8" waterline. Contractor worked on line And placed (1) fire hydrant and sta And back filled system living fitting excess-able to pour restraints.		
Informational:				
3	Misc	On Thursday, 7-29-2021 Red Ford Excavating began placement of the 8" waterline. Contractor worked on line And placed (1) fire hydrant and sta And back filled system living fitting excess-able to pour restraints.		
		-	Ford Excavating Resumed with inline hydrant. Contra	
Informational:				
4	Misc	waterline. Contractor wo	ed Ford Excavating began p rked on line And placed (1 ring fitting excess-able to po) fire hydrant and sta

On Friday, 7-30-2021. Red Ford Excavating Resumed waterline installation.

Contractor placed line #3 with inline hydrant. Contractor back field waterline but left fittings open to pour restraints.

On Tuesday, 8-03-2021. RedFord Excavating resumed 8"water main installation. Contractor installed line #2 from sta 13+14/w 10+25 line #2 to 17+51. This includes all fittings and hydrant at sta 16+47.

Informational:

5 Misc

On Thursday, 7-29-2021 Red Ford Excavating began placement of the 8" waterline. Contractor worked on line And placed (1) fire hydrant and sta. . And back filled system living fitting excess-able to pour restraints.

On Friday, 7-30-2021. Red Ford Excavating Resumed waterline installation. Contractor placed line #3 with inline hydrant. Contractor back field waterline but left fittings open to pour restraints.

On Tuesday, 8-03-2021. RedFord Excavating resumed 8"water main installation. Contractor installed line #2 from sta 13+14/w 10+25 line #2 to 17+51. This includes all fittings and hydrant at sta 16+47.

On Wednesday, 8-04-2021. Redford Excavating resumes water line installation for line #2 & #3. Contractor poured all restraints from areas that were installed previous.

On Thursday, 8-05-2021. Contractor resumed water line installation for line #2 and poured restraints and backfilled waterlines,

Informational:

6 Misc

On Thursday, 7-29-2021 Red Ford Excavating began placement of the 8" waterline. Contractor worked on line And placed (1) fire hydrant and sta. . And back filled system living fitting excess-able to pour restraints.

On Friday, 7-30-2021. Red Ford Excavating Resumed waterline installation. Contractor placed line #3 with inline hydrant. Contractor back field waterline but left fittings open to pour restraints.

On Tuesday, 8-03-2021. RedFord Excavating resumed 8"water main installation. Contractor installed line #2 from sta 13+14/w 10+25 line #2 to 17+51. This includes all fittings and hydrant at sta 16+47.

On Wednesday, 8-04-2021. Redford Excavating resumes water line installation for line #2 & #3. Contractor poured all restraints from areas that were installed previous.

On Thursday, 8-05-2021. Contractor resumed water line installation for line #2 and poured restraints and backfilled waterlines,

On Monday, 8-09-2021. Redford Excavating resumed water main installation on line #2. Contractor completed line #2, backfilled and poured all restraints for that line. Also 2nd crew constructed valve connections for construction taps on 16" main for Wednesday morning, both locations.

Informational:

7 Misc

On Thursday, 7-29-2021 Red Ford Excavating began placement of the 8" waterline. Contractor worked on line And placed (1) fire hydrant and sta. . And back filled system living fitting excess-able to pour restraints.

On Friday, 7-30-2021. Red Ford Excavating Resumed waterline installation. Contractor placed line #3 with inline hydrant. Contractor back field waterline but left fittings open to pour restraints.

On Tuesday, 8-03-2021. RedFord Excavating resumed 8"water main installation. Contractor installed line #2 from sta 13+14/w 10+25 line #2 to 17+51. This includes all fittings and hydrant at sta 16+47.

On Wednesday, 8-04-2021. Redford Excavating resumes water line installation for line #2 & #3. Contractor poured all restraints from areas that were installed previous.

On Thursday, 8-05-2021. Contractor resumed water line installation for line #2 and poured restraints and backfilled waterlines,

On Monday, 8-09-2021. Redford Excavating resumed water main installation on line #2. Contractor completed line #2, backfilled and poured all restraints for that line. Also 2nd crew constructed valve connections for construction taps on 16" main for Wednesday morning, both locations.

On Wednesday, 8-11-2021, Redford Excavating worked installing the water line at the entrance of the project and contractor put together the 12" valves for the 12" main tie-in for tomorrow. The lone property that would have been affected was notified of the shut.

On Thursday, 8-12-2021. The contractor completed both main tap and restored the water main back by 11;00 am. Water Services came out to assist with restoring the water in service.

Comments: