



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20212431, Public Works Right of Way Permit

Address: 111 NW JOSHUA DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Wednesday, August 18, 2021

**Corrective Action Required**

1	Misc	Site Visit - The line has not been installed yet.
---	------	---

**Comments:**