

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211416
Address: 1909 NE CATALINA AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Thursday, August 26, 2021

Corrective Action Required:

1	Misc	-Anchor garage PHF wall with 2" washer. Anchor must be within middle 1/3 of sill plate
		-Over-notched joists above garage
		-Fb garage/stair double stud wall from soffit **fb gap
		-Install security blocking for deck door
		-Install hanger at stair floor opening triple joist connection
		 **OK TO INSULATE

Comments: