



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20213803, Public Works Right of Way Permit  
Address: 2017 SW OSAGE DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Thursday, August 26, 2021

**Corrective Action Required**

1	Misc	Site Visit - No workers onsite, most pedestals are installed and conduit is in. There is a Spectrum vault that appears to be needing to be installed. There are some pits that are open that have conduit sticking out that need to be fenced off.
---	------	--

**Comments:**