

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20202637  
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Robb Popp	Partial	Thursday, August 26, 2021

Informational:

1	FIRST FLOOR	<b>**AREAS APPROVED**</b>
---	-------------	---------------------------

-SHAFT LAYER AT BUILDING A/B SEPARATION WALL BOTH SIDES  
-SCREW PATTERN AND FIRE TAPE SHAFT WALL BUILDING A

Corrective Action Required:

2	Miscellaneous Correction	-SEAL GAP AT TOP OF SECOND LAYER AND ALL PENETRATIONS AT SHAFT WALL BUILDING A
---	--------------------------	--

Corrective Action Required:

3	SECOND FLOOR	-SHAFT WALL LAYER AT BUILDING A -BETWEEN FLOOR SEPARATION AT BUILDING A/B SHAFT WALLS -SHAFT LAYER AT MECHANICAL/ PLUMBING CHASES ROOMS A218,A214
---	--------------	---

**Comments:**