

EVERSTEAD

600 SW JEFFERSON ST, SUITE 300 LEE'S SUMMIT, MISSOURI 64063 (816) 399 -4901

Inspector			ction Date	Time		
Colby Shaw		7/21/2021		2:30		
Address	City	Permi	# Owner/Builder			
1422 SW Georgetown	Lee's Summit	PRRES20211949 Sur		Summit Ho	Summit Homes	
Inspection Type		Subdivision		I.	Lot#	
Footing		Reserve at Stoney Creek		k	79	
Site Conditions (all must comply if applicable) Erosion control is in place and functional		Slab (Basement or Garage As Marked) ☐ Formed & Reinforced Per City Approved Dwgs				
 (inspection shall not be performed if erosion control is not functionally in compliance with the City requirements). ✓ Soils – bearing capacity as determined by: 			Garage structural slab pe Basement slab on grade p 6 mil vapor barrier install			
☐ Bearing on undisturbed soil @ 1,500 psf ☐ Per engineer report (comment or attach report)			slab Isolation rings or block-o pads for columns	outs are provided over pier		
Cold weather protection			<u>Footings</u>			
Foundation Wall Elements Wall forms centered on footings Wall thickness as specified on approved plans Reinforcement installed per approved plans Hold downs placed and installed properly Wall openings installed in accordance with City approved plans Deck/porch/balcony columns Top of wall and steps formed a minimum of 8″ above proposed grading contours. Max. 12″ block down at garage doors. Ufer Ground attachment rod left exposed (Give approx. location in comments)			Deck/porch/balcony foot Footing – width, depth ar or engineer report Solid jumps Frost depth (min. 36 inch Column pads – basement Column/pad at garage str Ufer Ground attachment	ng – width, depth and location per approved plans and gineer report lumps depth (min. 36 inches)		
			Pier foundation per approved plan Size: Depth: Bearing:			
Retaining walls (for multiple clarify which walls are being comments) Installation per approved plan	g inspected in the					
Comments:						
Concrete forms and installation of rebar are installed per approved plans and specifications. Footings rest on piers. Footings are approved for concrete. Ufer rod is located near the center of the rear garage wall.						

This is to certify that I, or qualified individuals working under my direction, inspected and/ or tested the above checked items in accordance with the applicable City approved building and site plans, codes and engineering details. The work is complete and to the best of my knowledge was found to be in substantial compliance with the approved plans and specifications.

Signed: Date:

7/21/2021

