## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20191614

Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Robb Popp Partial Thursday, September

02, 2021

Commercial

Informational:

1 THIRD FLOOR —AREAS APPROVED—

\*\*\*BUIDING C\*\*\*

**COMPLETE** 

\*\*\*BUILDING B\*\*\*

**COMPLETE** 

\*\*\*BUILDING A\*\*\*\*

-COMPLETE

Informational:

2 SECOND FLOOR —AREAS APPROVED—

\*\*\*BUILDING C\*\*\*

COMPLETE

\*\*\*BUILDING B\*\*\*

**COMPLETE** 

\*\*\*BUILDING A\*\*\*

CORRIDOR CEILINGS TO SHAFT WALL

ROOMS: 2001,2002, 2017,2018,2043, 2045,2046, 2047

STAIRWELL WALLS AND CEILING

Informational:

3 FIRST FLOOR —AREAS APPROVED—

\*\*\*BUILDING C\*\*\*

CORRIDOR CEILINGS TO SHAFT WALL

ROOMS:1015,1017,1020-1030 STAIRWELL WALLS AND CEILING

\*\*\*BUILDING B\*\*\*

CORRRIDOR CEILNGS TO SHAFT WALL

ROOMS: 1002-1015

STAIRWELL WALLS AND CEILING

\*\*\*BUIDING A\*\*\*

CORRIDOR CEILNG TO SHAFT WALL EXTERIOR WALL 1032 OK TO INSULATE

STAIRWELL WALLS AND CEILING

ROOMS: 1016,1018,1041,1042,1043,1044,1046,1050, 1053, 1053A, 1056, 1059, 1061, 1062, 1037,1038,1049,1052,1061, 1045,1047,1048,1057,1057A,1058

ROOM 1041 OK FOR SOFFIT FRAMING STAIRWELL WALLS AND CEILING

\*\*MCAL BUILDING\*\*

PRE ROCK:

MECHANICAL ROOM 165 NORTH WALL

ROOM 156 Kitchen 164 OK

CORRIDOR 167 TO 10' FROM SHAFT WALL

CORRIDOR 169 TO RM 123 CORRIDOR 172 TO RM 110 CORRIDOR 173 TO RM 102

UNITS: 102-147

Corrective Action Required:

4 Miscellaneous Correction

2044-INCOMPLETE 2045-INCOMPLETE 024-REPAIR TRUSS

MCAL-

## Comments: