## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20202637

Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

In-wall Inspection Robb Popp Partial Friday, September 03,

2021

Informational:

1 FIRST FLOOR \*\*BUILDING A:

-FIRST FLOOR OK TO SHAFT WALL

-FUROUT WALLS A101,104,108,109,118A

\*\*BULDING B:

ROOMS: 103,105,106 AT SHAFT WALL OK

-FIRST FLOOR EXCEPT FUROUTS OK TO BUILDING C

\*\*\*BUILDING F

-PLUMBING FOR DRINKING FOUNTAIN VESTIBULE F102

Informational:

2 SECOND FLOOR \*\*BUILDING A:

- COMPLETE

\*\*BUILDING B
-COMPLETE

**Comments:**