CITY OF LEE'S SUMMIT **Development Services Department** 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20191614

Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection -Robb Popp Failed Wednesday,

Commercial

September 08, 2021

Informational:

THIRD FLOOR 1 -AREAS APPROVED-

> ***BUIDING C*** **COMPLETE**

BUILDING B

COMPLETE

BUILDING A*

-COMPLETE

Informational:

2 SECOND FLOOR -AREAS APPROVED-

BUILDING C

COMPLETE

BUILDING B

COMPLETE

BUILDING A

CORRIDOR CEILINGS TO SHAFT WALL

ROOMS: 2001,2002, 2017,2018,2043, 2045,2046, 2047

STAIRWELL WALLS AND CEILING

Informational:

3 FIRST FLOOR

-AREAS APPROVED-

BUILDING C

CORRIDOR CEILINGS TO SHAFT WALL

ROOMS:1015,1017,1020-1030 STAIRWELL WALLS AND CEILING

BUILDING B

CORRRIDOR CEILNGS TO SHAFT WALL

ROOMS: 1002-1015

STAIRWELL WALLS AND CEILING

BUIDING A

CORRIDOR CEILNG TO SHAFT WALL EXTERIOR WALL 1032 OK TO INSULATE

STAIRWELL WALLS AND CEILING

ROOMS: 1016,1018,1041,1042,1043,1044,1046,1050, 1053, 1053A, 1056, 1059, 1061, 1062, 1037,1038,1049,1052,1061, 1045,1047,1048,1057,1057A,1058

ROOM 1041 OK FOR SOFFIT FRAMING

STAIRWELL WALLS AND CEILING

MCAL BUILDING

--- PRE ROCK:

MECHANICAL ROOM 165 NORTH WALL

ROOM 156

Kitchen 164 OK

CORRIDOR 167 TO 10' FROM SHAFT WALL

CORRIDOR 169 TO RM 123 CORRIDOR 172 TO RM 110 CORRIDOR 173 TO RM 102

SHARED SPACES OK FOR RC 150-174

UNITS: 102-147

Corrective Action Required:

Miscellaneous Correction 2044-INCOMPLETE 2045-INCOMPLETE 024-REPAIR TRUSS

MCAL-

Comments: