## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20191614 Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
All Rough Inspection - Commercial		Robb Popp	Partial	Monday, September 13, 2021
Informational: 1 THIRD FLOOR		—AREAS APPROVED—		
Informatio 2	onal: SECOND FLOOR	***BUIDING C*** COMPLETE		
		***BUILDING B*** COMPLETE		
		***BUILDING A**** -COMPLETE		
		—AREAS APPROVED—		
		***BUILDING C*** COMPLETE		
		***BUILDING B*** COMPLETE		
		***BUILDING A*** CORRIDOR CEILINGS TO SH	IAFT WALL	

ROOMS: 2001,2002, 2017,2018,2043, 2045,2046, 2047 STAIRWELL WALLS AND CEILING

Informational: 3 FIRST FLOOR

—AREAS APPROVED—

\*\*\*BUILDING C\*\*\* CORRIDOR CEILINGS TO SHAFT WALL ROOMS:1015,1017,1020-1030 STAIRWELL WALLS AND CEILING

\*\*\*BUILDING B\*\*\* CORRRIDOR CEILNGS TO SHAFT WALL ROOMS: 1002-1015 STAIRWELL WALLS AND CEILING

\*\*\*BUIDING A\*\*\* CORRIDOR CEILNG TO SHAFT WALL EXTERIOR WALL 1032 OK TO INSULATE STAIRWELL WALLS AND CEILING ROOMS: 1016,1018,1041,1042,1043,1044,1046,1050, 1053, 1053A, 1056, 1059, 1061, 1062, 1037,1038,1049,1052,1061, 1045,1047,1048,1057,1057A,1058 ROOM 1041 OK FOR SOFFIT FRAMING STAIRWELL WALLS AND CEILING

\*\*MCAL BUILDING\*\* --- PRE ROCK: MECHANICAL ROOM 165 NORTH WALL ROOM 156 Kitchen 164 OK CORRIDOR 167 TO 10' FROM SHAFT WALL CORRIDOR 169

SHARED SPACES OK FOR RC 150-174

UNITS: 102-147

Corrective Action Required: 4 Miscellaneous 2044-INCOMPLETE Correction 2045-INCOMPLETE 024-REPAIR TRUSS MC- Units 1-18- support mc, install putty packs, nail corners, finish plumbing in 11, install all anchor bolts

Comments: