

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20191614
Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Robb Popp	Partial	Wednesday, September 22, 2021

Informational:
1 THIRD FLOOR —AREAS APPROVED—

BUILDING C
COMPLETE

BUILDING B
COMPLETE

BUILDING A*
-COMPLETE

Informational:
2 SECOND FLOOR —AREAS APPROVED—

BUILDING C
COMPLETE

BUILDING B
COMPLETE

BUILDING A
CORRIDOR CEILINGS TO SHAFT WALL

Informational:
3 FIRST FLOOR

COMPLETE EXCEPT 2044

— AREAS APPROVED —

BUILDING C

CORRIDOR CEILINGS TO SHAFT WALL

ROOMS: 1015, 1017, 1020-1030

STAIRWELL WALLS AND CEILING

BUILDING B

CORRIDOR CEILINGS TO SHAFT WALL

ROOMS: 1002-1015

STAIRWELL WALLS AND CEILING

BUILDING A

CORRIDOR CEILING TO SHAFT WALL

EXTERIOR WALL 1032 OK TO INSULATE

STAIRWELL WALLS AND CEILING

ROOMS: 1016, 1018, 1041, 1042, 1043, 1044, 1046, 1050, 1053, 1053A, 1056, 1059, 1061, 1062, 1037, 1038, 1049, 1052, 1061, 1045, 1047, 1048, 1057, 1057A, 1058

ROOM 1041 OK FOR SOFFIT FRAMING

STAIRWELL WALLS AND CEILING

SOFFIT FRAMING 1049, 1052, CORRIDOR 1060, 1036

MCAL BUILDING

--- PRE ROCK:

MECHANICAL ROOM 165 NORTH WALL

ROOM 156

Kitchen 164 OK-CEILING OK FOR ROCK NOT AT HOODS

CORRIDOR 167 TO 10' FROM SHAFT WALL

CORRIDOR 169, 172, 173, 34, 39, 42

MC EXTERIOR WALLS OK FOR FOAM

MC SHARED SPACES OK FOR RC 149-160, 162, 162A, 174, 174A, 175

MC UNITS 1-18, 21, 36, 37

SHARED SPACES: 149, 150, 152, 153, 154, 157, 159, 162, 174, 174A, 175

AL UNITS: 102-147

Corrective Action Required:
4 Miscellaneous
Correction

2044-INCOMPLETE

2045-INCOMPLETE

024-REPAIR TRUSS

COMPLETE DRY SYSTEM IN ATTIC

Comments: