

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20202637  
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Underground Electrical Inspection - Commercial</b>	Robb Popp	Partial	Wednesday, September 22, 2021

Informational:

1 Misc

3/4/21, 3/5/21 - INSPECTED PARTIAL UNDERGROUND CONDUIT FOR JOB TRAILER TEMP POWER, RUNNING E TO W ALONG N SIDE OF GRAVEL DRIVE

- Conduit in main electrical g110 for first service bundle
- Conduit from main electrical room to areas A, B & C through area D
- Conduit for future musco light at left field, Southeast diamond
- Conduit for future musco lights at outfield for Southwest diamond
- Conduit south side of field house from electrical room to musco/ future musco lighting
- Conduit from field house east to NE 3rd base dugout and musco light, and north to NW 3rd base field and musco light, to RF Musco light and scoreboard, to NW right field quaside box and to east and west monument signs
- Conduit from fieldhouse to NE field dugouts and south Musco lighting and water pump to 10' East of RF bullpen, SE field future lighting and dugout power, and scoreboard

LIGHT POLES:

-Conduit and ground rods to P2-4,7-17,19-21,24,25, 30-37-41,43-51, 53-56,56B,56A,59,64,65,65A,65B,66-71

**Comments:**