

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20203845
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underground Electrical Inspection - Commercial	Robb Popp	Partial	Wednesday, September 29, 2021

Informational:

1	THE FOLLOWING AREAS ARE APPROVED	-Conduit from Southwest corner of building north to CT and Transformer location -Conduit for monument sign at Northeast entrance and Left field Musco light at northeast diamond to west end of NE diamond -Conduit for left field Musco light at NW diamond -Conduit from NW dugout electrical room to scoreboards -Conduit between north fields to NW dugout and field house for musco lights, power and communications -Conduit for (4) batting cages between 2 north fields
---	----------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Comments: