



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20214884, Public Works Right of Way Permit  
Address: 121 SE 3RD ST, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Wednesday, September 29, 2021

**Corrective Action Required**

1      Misc

Site Visit - Bob Burns, Steve Proudfit , Nick Scott and I met onsite with the crew that was working on locating the utilities in the alley. A concern came up with the backfill and the ability to protect the gas main with dirt and keeping the dirt in place. Ryan Riddel was contacted by the worker onsite and Steve Proudfit spoke with Ryan over coming up with a solution. To be determined at this time.

**Comments:**