



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20214308, Public Works Right of Way Permit  
Address: 1904 NE PARK RIDGE DR, LEES SUMMIT, MO 64064

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Passed	Thursday, September 30, 2021

**Corrective Action Required**

1	Misc	Site Visit - The service line has been installed. They had bored across the street and into lot that was not established yet. No damage to the road from the bore.
---	------	--

**Comments:**