



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20214528, Public Works Right of Way Permit

Address: 1516 SW SUGAR TREE DR, LEES SUMMIT, MO 640821520 SW SUGAR TREE DR, LEES SUMMIT, MO 640821519 SW SUGAR TREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Partial	Thursday, September 30, 2021

Corrective Action Required

1	Misc	Site Visit - The line may have been bored across the street but cable is still in the yard of 1519. Monitoring.
---	------	---

Comments: