CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20212446 Address: 4805 NE FREEHOLD CT, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
All Rough Inspection - Residential		Khanh Nguyen	Failed	Tuesday, October 05, 2021	
Correctiv	ve Action Required	:			
1	-Support gas csst line every 32" an -Fb front basement bedroom wal exterior wall vertically every ten -Over notched joist outside bedro -Basement waste stack clean out -Support plumbing above baseme		rames per security cod p piping to outside ing return air space fror every 32" and min 3" ab edroom wall from I bea y every ten ft or less utside bedroom above I k clean out shall be acco	butside ir space from soffit above wet bar ad min 3" above bottom of joists from I beam soffit; fb same bedroom ft or less bom above hallway at toilet	
		**OK TO INSULATE			

Comments: