

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20203793  
Address: 157 NW CARSON DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Robb Popp	Failed	Tuesday, October 05, 2021

Corrective Action Required:

1	Misc	-Garage PFH-support end of header -Install stud shoes at over-bored laundry wall roof-support -double Stud -S trap above basement bathroom toilet not allowed-Complete pex, connect bath exhaust, Fb floor penetration -Submit engineer letter for ridge I beam in place of triple 24" lvl beam
---	------	--

**\*\*DO NOT INSULATE**

**Comments:**