

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20202637  
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Robb Popp	Partial	Tuesday, October 05, 2021

Informational:

1	FIRST FLOOR	<b>**AREAS APPROVED**</b>
---	-------------	---------------------------

- SHAFT LAYER AT BUILDING A/B SEPARATION WALL BOTH SIDES
- SCREW PATTERN AND FIRE TAPE SHAFT WALL BUILDING A
- SHAFT LAYER AT BUILDING C/D SEPARATION WALL
- SCREW PATTERN AT SHAFT WALL BUILDING C
- SHAFT LAYER AT ELEVATOR BUILDING B
- ABOVE CEILING RATING AT A11, A14

Corrective Action Required:

2	Miscellaneous Correction	-SEAL GAPS AND PENETRATIONS AT ELEVATOR SHAFT
---	--------------------------	---

Corrective Action Required:

3	SECOND FLOOR	<ul style="list-style-type: none"><li>-SHAFT WALL LAYER AT BUILDING A</li><li>-BETWEEN FLOOR SEPARATION AT BUILDING A/B SHAFT WALLS</li><li>-SHAFT LAYER AT MECHANICAL/ PLUMBING CHASES ROOMS A218,A214</li><li>-ABOVE CEILING RATING AT A25, A26</li><li>-SHAFT LAYER AT CHASE B211</li></ul>
---	--------------	--

**Comments:**