

Third Party Inspection Report

Inspector	Date	Time							
David P. Ainsworth, P.E.	9-29-21	3:08 PM							
Company	Permit #	Permit Holder							
David P. Ainsworth, P.E.	2021-3403 Address OSAGE LOT 30	CLANTON PEORETH							
Inspection Type	Address OSAGE LOT 30	9							
FOOTING	2117 SW RUTHERFORD DR LSMO								
E-Mail Address dainsworth@chelepis.co	m								
Instructions: This form must be co	mpleted when performing a third p	arty inspection for any building							
permit in Lee's Summit. Submit form Department. If a subsequent inspection being scheduled.		A PROCESS OF PROPERTY AND A STANDARD CONTRACTOR OF THE STANDARD CONTRACTOR							
Check all boxes that apply to the site of	onditions and the inspection being	performed.							
Site Conditions:									
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)									
Erosion controls in place and r	naintained								
*Note: If these requirements are not r	net no inspection shall be performe	d or accepted by the City.							
Foundations and Footings:									
Foundation type and MBOE is	Foundation type and MBOE is equal to or above the plot plan								
Concrete encased electrode (u	Concrete encased electrode (ufer) ground installed (Location must be noted in comments)								
Foundation/Footing meets all engineered design.	Foundation/Footing meets all City Code requirements and matches City approved plans or engineered design.								
Foundation Walls:									
Elevation is sufficient to achiev	ve 2% slope away from structure								
No openings below the MBOE									
Concrete encased electrode (ufer) ground exposed								
Foundation wall meets all City engineered design.	Code requirements and matches Ci	ty approved plans or							



_									
-	1	a	r	Y	1	1	3	σ	
	8	CI	u	U	8 8	u	в	8	

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

UFER GROUND ROD ON RIGHT SIDEWALL ABOUT 6'BEHIND FRONT RIGHT CORNER.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.



Dail P. answort

Engineer/Architect Seal