



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20214104, Public Works Right of Way Permit

Address: 1917 NE CATALINA AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Matt Munger	Passed	Wednesday, October 06, 2021

Corrective Action Required

1	Misc	Site Visit - The service line has been installed. The yard was not established prior to Spires work. This is a new home build.
---	------	--

Comments: