

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211896
Address: 4716 NE JAMESTOWN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Wednesday, October 13, 2021

Corrective Action Required:

1	Misc	-Nail exterior wall siding and sheathing to per code ** check later
		-Install spark ring at outdoor receptacle box near AC
		-Install collar ties per code above front bedroom
		-Support hip rafters above great room I beam
		-Support bottom of hip rafter above front bedroom closet
		-Pan off parallel electrical within return air space at wet bar
		-Seal penetrations of ceiling return air space above wet bar
		-Fb basement bedroom and bathroom wall from soffit. Fb all gaps and openings **1st, cannot use 7/16" sheathing to fire block; 2nd, there are too many gaps that need to be fb. Look closely

**OK TO INSULATE

Comments: