

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20202637
Address: 1001 SE BAILEY RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	Robb Popp	Partial	Wednesday, October 13, 2021

Informational:

1 FIRST FLOOR

****BUILDING A:**
-COMPLETE

****BUILDING B:**
ROOMS: 103,105,106 AT SHAFT WALL OK
-FIRST FLOOR EXCEPT FURROUTS OK TO BUILDING C

*****BUILDING C:**
FIRST FLOOR EXCEPT FURROUTS

*****BUILDING F**
-PLUMBING FOR DRINKING FOUNTAIN VESTIBULE F102

****BUILDING G**
-PLUMBUING FOR BATHROOMS 108C, 108D
-DWV AT BLOCK WALLS IN SERVERY AND AL A CARTE G102,103

Informational:

2 SECOND FLOOR

****BUILDING A:**
- COMPLETE

****BUILDING B**

-COMPLETE

**BUILDING C

-COMPLETE EXCEPT FUR OUT WALLS AND AT SHAFT WALL TIE INS

Comments: