

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20191614  
Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Commercial</b>	Robb Popp	Partial	Wednesday, October 13, 2021

Informational:	
1      THIRD FLOOR	— AREAS APPROVED —
	***BUILDING C***
	COMPLETE
	***BUILDING B***
	COMPLETE
	***BUILDING A***
	-COMPLETE EXCEPT ELEVATOR

Informational:	
2      SECOND FLOOR	— AREAS APPROVED —
	***BUILDING C***
	COMPLETE
	***BUILDING B***
	COMPLETE
	***BUILDING A***
	COMPLETE EXCEPT ELEVATOR

Informational:

3 FIRST FLOOR

—AREAS APPROVED—

\*\*\*BUILDING C\*\*\*  
COMPLETE

\*\*\*BUILDING B\*\*\*  
COMPLETE

\*\*\*BUILDING A\*\*\*  
CORRIDOR CEILING TO SHAFT WALL  
EXTERIOR WALL 1032 OK TO INSULATE  
STAIRWELL WALLS AND CEILING  
ROOMS: 1016,1018,1041,1042,1043,1044,1046,1050, 1053, 1053A, 1056, 1059,  
1061, 1062, 1037,1038,1049,1052,1061, 1045,1047,1048,1057,1057A,1058  
ROOM 1041 OK FOR SOFFIT FRAMING  
STAIRWELL WALLS AND CEILING  
SOFFIT FRAMING 1049,1052, CORRIDOR 1060,1036

\*\*MCAL BUILDING\*\*  
--- PRE ROCK:  
MECHANICAL ROOM 165 NORTH WALL  
ROOM 156  
Kitchen 164 OK-CEILING OK FOR ROCK NOT AT HOODS  
CORRIDOR 167 TO 10' FROM SHAFT WALL  
CORRIDOR 169,172,176,177a,177, 173, 34,39,42,48  
MC EXTERIOR WALLS OK FOR FOAM  
MC SHARED SPACES OK FOR RC 149-160, 162,162A,163,174, 174A,175,179A,179  
  
MC UNITS 1-18, 21,24-33, 36,37,45,46  
SHARED SPACES: 149,150,152,153,154,157,159,161,162, 162A,174,174A,175  
AL UNITS: 102-147

Corrective Action Required:

4 Miscellaneous  
Correction

024-REPAIR TRUSS  
COMPLETE DRY SYSTEM IN ATTIC

Comments: