

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20212323
Address: 532 SE CARTER RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Robb Popp	Failed	Thursday, October 14, 2021

Corrective Action Required:

1	Misc	-Finish lookouts in garage -Solid block and nail horizontal seams at single car bay sheathing and nail -Address sheathing not nailed to top plate west exterior wall, master bed north, bed 3 East -Provide proper slope at vent lines in attic -Solid block and nail sheathing seams at master bed header 2 -Block and nail seam above window bed 2 -Seal joist space penetrations in return air
---	------	---

Comments: