



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20212404, Public Works Right of Way Permit
Address: 127 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Nick Scott	Passed	Friday, October 22, 2021

Corrective Action Required

1	Misc	Site Visit - The service line has not been installed yet.
---	------	---

Corrective Action Required

2	Misc	Site visited and gas line is installed passed
---	------	---

Comments: