



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20214816, Public Works Right of Way Permit  
Address: 1513 SW SUGAR TREE DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Nick Scott	Partial	Friday, October 22, 2021

Corrective Action Required	
1      Misc	Site visited does not look like any work has started will come back in a week to check again

**Comments:**