



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20213802, Public Works Right of Way Permit

Address: 2051 SE SHENANDOAH DR, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

| Inspection:                  | Inspector:  | Outcome: | Date:                      |
|------------------------------|-------------|----------|----------------------------|
| <b>Site Visit Inspection</b> | Matt Munger | Passed   | Tuesday, November 02, 2021 |

**Corrective Action Required**

|   |      |                                                                                  |
|---|------|----------------------------------------------------------------------------------|
| 1 | Misc | Site Visit - The poles are in and grass is growing in around the poles. Closing. |
|---|------|----------------------------------------------------------------------------------|

**Comments:**