CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20212953

Address: 517 SE CARTER RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Tuesday, November

Residential 02, 2021

Corrective Action Required:

1 Misc -address over notched studs on garage east wall

-all anchor bolts must be in the middle 1/3 of bottom plate

-all BOCA plates in garage to extend 2" above bottom plate

-Over notched studs west wall garage

-strap top plate garage/laundry lapped less than 24"

-stop top play garage entry lapped less than 24"

-address over notched stud in bearings wall at garage/laundry

-fire block botton plate penetrations

-fb hole in floor left of fireplace

-provide proper slope for dwv in attic

-nail corner and intersecting walls per code

-fb floor penetrations

-complete interior wall bracing per plan lib to be 8' min

-complete soffit Line fire blocking though out

-strike plate at kitchen/dining wall

-provide hanger or 11/2" bearing for rafter at bedroom 3

-fire block dwv at bath one shower bottom plate

-address se corner not tie together at top plate

-address over notched load bearing studs at dining room/master & hallway

closet

-midway strap at dwv at hallway closet

- -address roof bearing on non load bearing wall at laundry
- -complete blocking of joists parallel with foundation per plan
- -complete plumbing and exhaust fan in basement bath
- -fb above electrical panel
- -fire block dwv at top plate in basement bedroom closet
- -ufer and gec clamped to remain accessible at time of finish
- -solid blocking between joist space under kitchen island per plans

Comments: