

Alpha Omega Geotech, Inc 1701 State Avenue Kansas City, KS 66102 Phone: 913-371-0000

Footing Inspection Report

Client: Project:

LSPH Investors, LLC 21-390F

7939 Floyd Street Chipotle Lee's Summit Overland Park, KS 66204 1130 SE Oldham Pkwy Lee's Summit, MO

Activity Date: 10/26/2021 Technician: Marquez, Jeff

Time In: 11:30 **Time Out:** 15:30

Temperature (F): 58 Weather: Cloudy

If other, explain: Na

GENERAL OBSERVATIONS

Location of Footings Inspected: Grade beam @ A-B/1-5

Dimensions: 2x3 Depth: 3ft

Allowable Bearing Capacity (psf): 2000 Source Of Allowable Bearing Capacity:

Project Plans

If Project Plans, Sheet No.: S000

FIELD OBSERVATIONS

Visual Description of Material Exposed In Base Of Footing Excavation: Brown lean/fat clay with screenings

Uniform Bearing conditions Throughout 100% Of The Footing Excavation: Yes

Range Of Pocket Penetrometer Readings: 7000-9000

Soft Areas/Soft Underlying Layers of Soil Encountered by Probing with T-Probe: No

Footing Excavation Properly Squared: Yes

Footing Excavation Free Of All Ponded Water: Yes

Are There Non-Compliance Items: No