

Alpha Omega Geotech, Inc 1701 State Avenue Kansas City, KS 66102 Phone: 913-371-0000

Footing Inspection Report

Client: Project:

LSPH Investors, LLC 21-390F

7939 Floyd Street Chipotle Lee's Summit Overland Park, KS 66204 1130 SE Oldham Pkwy Lee's Summit, MO

Activity Date: 11/15/2021 Technician: Lipp, Carmen

Time In: 11:00 Time Out: 14:00

Temperature (F): 62 Weather: Partly Cloudy

If other, explain: Na

GENERAL OBSERVATIONS

Location of Footings Inspected: South dumpster enclosure

Dimensions: 3'x1.5'

Depth: 3'

Allowable Bearing Capacity (psf): 2000 Source Of Allowable Bearing Capacity:

Project Plans

If Project Plans, Sheet No.: S000

FIELD OBSERVATIONS

Visual Description of Material Exposed In Base Of Footing Excavation: Brown lean/fat clay with screenings

Uniform Bearing conditions Throughout 100% Of The Footing Excavation: Yes

Range Of Pocket Penetrometer Readings: 3000-7000 psf

Soft Areas/Soft Underlying Layers of Soil Encountered by Probing with T-Probe: No

Footing Excavation Properly Squared: Yes

Footing Excavation Free Of All Ponded Water: Yes

Are There Non-Compliance Items: No