



PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20214105, Public Works Right of Way Permit
Address: 1913 NE CATALINA AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Nick Scott	Passed	Thursday, November 18, 2021

Corrective Action Required

1 Misc

Site Visit - The gas service line has been installed. They did bore under the road. The depth marks on the road indicate that they bored well over 3ft meeting our depth requirements. They did take out a sidewalk panel but backfilled with gravel. The yard across the street has seed and straw put down. Will monitor restoration. (Pics taken of the road depth marks and sidewalk).

Comments: